

Upgrade Set to New INTERBUS Field Bus System

TIP B-1020

Controls

Benefits:

- Easier spare parts availability
- Operator friendly
- Enhanced diagnostic feature
- Original INTERBUS field bus installation can still be used, no installation change

Safety



Obsolescence



Quality



Cost Reduction



Performance



Maintenance



After

Upgrade Set to New INTERBUS Field Bus System

Machine Model for Improvement: All BWP Bielomatik P 25-85 banknote sheeter machines with INTERBUS DSC card.

Description of Improvement:

This upgrade is part of the Technical Improvement Program (TIP).

BW Papersystems will replace the obsolete INTERBUS card in the S7-rack by an upgrade package to emulate the INTERBUS system structure with new hardware and enhanced diagnostic functionality.

Upgrade Set to New INTERBUS Field Bus System

Preconditions:

- Machine is equipped with INTERBUS DSC card, and Siemens S7 CPU 4xx Version $\geq$ V 5.0 ready for firmware upgrade
- Replacement will be done in +H18 electronic cabinet
- The selection of the INTERBUS card to be replaced is made by BWP according to the existing fieldbus topology

Included in this TIP:

- All required parts
- Necessary engineering
- Updated documentation pages for relevant sections

Estimated downtime, no production:

- 2,5 Days

Estimated startup, limited production:

- 0,5 Day

Estimated monitoring in production:

- 1 Day

Required manpower:

- 1 BW Papersystems Electrical Field Service Engineer for 4 days